ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalakunte
Street ID	**Street Name**	**Significant Landmark**
W0549	NA	Bagalgunte Main Road
Segment No.	**Total Length (m)**	
14/S-W0549/S045608	131.51	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	131.51	77.502816	13.056999	77.502681	13.055817	Hesaraghatta Main Road	9th Main

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains at Bagalagunte main road left side	1700000	2016
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender		014-16-000010
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/32/15-16	24/03/2015	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N.Shivananda		1531733.00
Phone No.	**E-Mail ID**	
9901829745		

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು